

INSPECTION REPORT

St Johns Bridge - Photo Demo

AI-assisted photo review

LOCATION

Historical OregonDOT photographs - Portland

INSPECTOR

Demo Inspector

INSPECTION DATE

14 Sept 2026

STATUS

In progress

4 issues · **4 photographs**

INSPECTION BRIEF

Historical photo review. Highlight visible concrete condition and practical next steps. Confirm the work stage before proposing repairs.

Contents

	PAGE
#1 Concrete loss at the pier edge	3
#2 Exposed material along the arch edge	4
#3 Completed arches — overview record	5
#4 Bridge setting — closer photos needed	6
Summary	7
Sign-off	8

ISSUE #1

Concrete loss at the pier edge

Medium severity · Open

TRADE / AREA

Concrete Repair · Pier edge — historical photo

CATEGORY


Concrete

INSPECTOR NOTES

Concrete is missing along the pier edge, with exposed brown-coloured reinforcement and white staining. Confirm whether this is deterioration or preparation for repair.

Next step: Check the work stage and extent on site before deciding on repairs.

Photograph 1 of 1 · annotated



RECORDED

14 Sept 2026

ISSUE #2

Exposed material along the arch edge

High severity · Open

TRADE / AREA

Arch edge — historical photo

INSPECTOR NOTES

Human-reviewed note. Rough strips, local concrete loss and exposed material are visible along the arch edges. Confirm whether this records deterioration or repair preparation before specifying follow-up work. The photograph does not establish depth, cause or present condition.

Photograph 1 of 1



RECORDED

14 Sept 2026

ISSUE #3

Completed arches — overview record

Not assessed severity · Open

TRADE / AREA

Completed arches — historical photo

INSPECTOR NOTES

Human-reviewed note. Pale arch surfaces, form lines and the adjacent stairway are visible. No clear defect can be identified at this distance. Retain as an overview and obtain closer photographs for condition assessment. This image does not certify the work or its present condition.

Photograph 1 of 1



RECORDED

14 Sept 2026

ISSUE #4

Bridge setting — closer photos needed

Not assessed severity · Open

TRADE / AREA

Site overview — historical photo

INSPECTOR NOTES

Human-reviewed note. The bridge, river and shoreline are visible from a distance. Surface details are too small to assess specific defects. Record as a site overview and request close-ups of the areas requiring review. No conclusion about structural condition can be drawn from this image.

Photograph 1 of 1



RECORDED

14 Sept 2026

Summary

4 issues · 4 photographs

By severity

Critical: 0
High: 1
Medium: 1
Low: 0
Not assessed: 2

By status

Open: 4
In progress: 0
Resolved: 0
Closed: 0
Wont fix: 0

By trade

Concrete Repair: 1
Not assigned: 3

Sign-off

INSPECTOR
Demo Inspector

SIGN-OFF STATUS
Not signed off

SIGN-OFF DATE
Not recorded